

P-BA BARE FIBER ADAPTORS

Features:

- Easy to handle
- Environmentally stable


Applications:

- OTDR acceptance testing
- Power meter hookup
- Approximate loss / continuity testing
- Talkset connection
- Visible fault location




Mechanical Drawings:


Unit: mm




P-BA-FC- □□□



P-BA-SC- □□□



P-BA-ST- □□□



P-BA-LC- □□□

Ordering Information:

P - BA - □□ - □□□

Connector Type

- FC FC type
- SC SC type
- LC LC type
- ST ST type
- XX Others, please specify

Ferrule Inner Diameter

- 125 125µm
- 126 126µm
- 127 127µm
- XXX Others, please specify.